


REPORT OF INSPECTION IN ACCORDANCE WITH THE MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL

1 name of issuing authority [redacted]  
 2 name of ship ESTONIA  
 3 date of inspection 27.09.1994  
 5 call sign ESTE  
 10 place of inspection TALLINN.

15 nature of deficiency code	text	Convention <sup>1</sup> references	16 action taken <sup>2</sup>
1284	Bow door		99
1280	Sounding pipe <u>Atk Eng. room</u>		17
0720	2 portable fire exting. <u>missing Eng. room</u>		17
0920	SAFETY PLAN		99
2010	MUSTER LIST		99
2030	DAMAGE CONTROL PLAN		99
2045	CARLO OPERATION MANUAL		99
0710	FIRE PREVENTION <u>N/A BRIDGE DOOR,</u> <u>BOILER ROOM CLOSING DEVICE MISSING</u> <u>FIRE DOOR IN GALLEY NOT WORKING PROPERLY</u>		17
1520	'OFF-COURSE' ALARM NOT INSTALLED		99
0745	MEANS OF CONTROL: <u>MIMIC PANEL</u>		99
2055	MANUALS AND INSTRUCTIONS ( <u>EM. GEN, BRIDGE ROUTINES, EM. HANDLING,</u> <u>STEERING GEAR, MANOUVRE CHARACTERISTICS</u> )		99
1260	WINDOWS IN GALLEY NOT POSSIBLE TO CLOSE		17 <i>7cl.</i>
1250	COVERS ON BULKHEAD OETIC TO BE CLOSED		17
1199	CARGO SECURING DEVICES		99



Continuing page  no  yes

name Head of National Ship. Inspect. Division  
 duly authorized surveyor  
 signature Alafine Alafine  
/Valguse/

Sjöv. 1 104 92 12 Sjöv Tryck.

1 To completed in the event of a detention.  
 2 Codes for actions taken include i.a.: ship detained/released, flag State informed, classification society informed, next port informed (for codes see reverse side of copy).  
 DOUG MAREL 6  
 2000002958

REPORT OF INSPECTION IN ACCORDANCE WITH THE MEMORANDUM OF UNDERSTANDING ON PORT STATE CONTROL

1 name of issuing authority [redacted]
2 name of ship ESTONIA
3 date of inspection 27.09.1994
5 call sign ESTE
10 place of inspection TALLINN.

Table with 4 columns: 15 nature of deficiency code, text, Convention references, 16 action taken. Rows include: 1284 Bow door, packing damage (99); 1280 Soundings pipe Max Eng. Form (17); 0720 2 portable fire exting. missing Eng. Form (17); 0920 SAFETY PLAN (99); 2010 MUSTER LIST (99); 2030 DAMAGE CONTROL PLAN (99); 2045 CARGO OPERATION MANUAL (99); 0710 FIRE PREVENTION NAV. BRIDGE DECK, BOILER ROOM CLOSING DEVICE MISSING, FIRE DOOR IN GALLEY NOT WORKING PROPERLY (17); 1520 'OFF-COURSE' ALARM NOT INSTALLED (99); 0745 MEANS OF CONTROL: MIPLC PANEL (99); 2055 MANUALS AND INSTRUCTIONS (EM. GEN., BRIDGE ROUTINES, EM. HANDLING SLEEPING ETC), MANOEUVER CHARACTERISTICS (99); 1260 WINDOWS IN GALLEY NOT POSSIBLE TO CLOSE (17); 1250 COVERS ON SULKHEAD DECK TO BE CLOSED (17); 1199 CARGO SECURING DEVICES (A FEW PIECES OF SEC. DEV WORNED OUT) (99).

Continuing page [ ] no [ ] yes

name Head of National Ship Inspection Department
duly authorized surveyor
Alfina Valgma

To be completed in the event of a deficiency

copy for... classification service...

NOU 1996 7
200002958

Preliminary version

# SUPPLEMENT

TO

THE FINAL REPORT ON THE CAPSIZING ON 28  
SEPTEMBER 1994 IN THE BALTIC SEA OF THE  
RO-RO PASSENGER VESSEL MV ESTONIA

Part I

The Joint Accident Investigation Commission  
of  
Estonia, Finland and Sweden